

Safety Issue Type: Recalls

August 28 2025 NHTSA Campaign Number: 25V559000

Unexpected Steering Wheel Movement

A steering wheel that moves unexpectedly may increase the risk of a crash.

NHTSA Campaign Number 25V559000

Manufacturer VinFast Auto, LLC

Components LANE DEPARTURE

Potential Number of Units Affected 6314

Summary

VinFast Auto, LLC (VinFast) is recalling certain 2023-2025 VF8 vehicles. The Advanced Driver Assistance System (ADAS) may activate during wide turns, causing unexpected steering wheel movements that are difficult for the driver to override.

Remedy

VinFast will update the ADAS software, free of charge. Owner notification letters are expected to be mailed October 24, 2025. Owners may contact VinFast customer service at 1-833-503-0600.

Notes

Affected Products (3)

Vehicle

MAKE	MODEL	YEAR
VINFAST	VF 8	2023-2025

Associated Documents (2)

- RCAK - Recall Acknowledgement
RCAK-25V559-5348.pdf 0.321KB
<https://static.nhtsa.gov/odi/rcl/2025/RCAK-25V559-5348.pdf>
- Recall 573 Report
RCLRPT-25V559-3549.pdf 0.385KB
<https://static.nhtsa.gov/odi/rcl/2025/RCLRPT-25V559-3549.pdf>